



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

November 17, 2006

Supervisor *[Signature]*

Mine Name: B & C Limestone Quarry
Operator Name: Bryce Haas

Permit number: M/039/013
Inspection Date: November 15, 2006
Time: 8:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: None.
Mine Status: Inactive (site being reclaimed)

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Check status of reclamation while in the area.

Inspection Summary:

1. Very little has been done since my last inspection. The salvaged construction materials from the office building have been removed. The only items remaining in the shop building are the saws. Demolition of this building has begun on the south west side.

I met one of Mr. Haas' employees at the gate. He informed me that Mr. Haas had meeting to attend and would not be around for most of the day. I was given the following phone numbers to be able to contact Mr. Haas: Office- 435-528-5342, cell - 801-367-0066

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor the site when in the area.

Inspector's Signature *[Signature]*

LK:pb

O:\M039-Sanpete\M0390013-BandCLimestone\inspections\insp-08312006.doc

Date: November 17, 2006